



## Product Change Notice

Micron PCN: 30993  
 Date: 10/14/2013

<b>Type of Change:</b>	End of Life, Die Shrink	
<b>Title of Change:</b>	2Gb T79M LPDDR End of Life Phase with Possible Replacement	
<b>Description of Change:</b>	<p>Micron's 42nm 2Gb LPDDR (T79M) products are being discontinued with possible replacements.</p> <p>For inquires on replacement parts, please contact <a href="mailto:mleighton@micron.com">mleighton@micron.com</a> or <a href="mailto:sdurnal@micron.com">sdurnal@micron.com</a>.</p>	
<b>Reason for Change:</b>	Change in Market Demand, Optimization of Manufacturing Efficiency	
<b>Contact Information:</b>	<p><u>Marketing Contact</u>          CARLY MAMIZUKA  <a href="mailto:CMAMIZUKA@MICRON.COM">CMAMIZUKA@MICRON.COM</a>          Micron Semiconductor Prds</p>	<p><u>Engineering Contact</u>          JOHN BEHREND  <a href="mailto:JBEHREND@MICRON.COM">JBEHREND@MICRON.COM</a>          Micron Semiconductor Prds</p>

**Product Affected:** 42nm 2Gb LPDDR (T79M)

<u>Affected Micron Part Number</u>	<u>Suggested Replacement Part</u>
MT46H128M16LFB7-5 AIT:B	MT46H128M16LFDD-48 AIT:C
MT46H128M16LFB7-5 IT:B	MT46H128M16LFDD-48 IT:C
MT46H128M16LFB7-5 WT:B	MT46H128M16LFDD-48 WT:C
MT46H128M16LFB7-6 IT:B	MT46H128M16LFDD-48 IT:C
MT46H128M16LFB7-6 WT:B	MT46H128M16LFDD-48 WT:C
MT46H128M32L2KQ-5 IT:B	MT46H128M32L2KK-48 WT:C
MT46H128M32L2KQ-5 WT:B	MT46H128M32L2KK-48 WT:C
MT46H128M32L2KQ-6 IT:B	MT46H128M32L2KK-48 WT:C
MT46H128M32L2KQ-6 WT:B	MT46H128M32L2KK-48 WT:C
MT46H128M32L2MC-5 WT:B	No Replacement
MT46H128M32L2MC-6 WT:B	No Replacement
MT46H256M32L4JV-5 IT:B	MT46H256M32L4SA-48 WT:C
MT46H256M32L4JV-5 WT:B	MT46H256M32L4SA-48 WT:C
MT46H256M32L4JV-6 WT:B	MT46H256M32L4SA-48 WT:C
MT46H256M32R4JV-5 IT:B	No Replacement
MT46H256M32R4JV-5 WT:B	No Replacement
MT46H256M32R4JV-6 IT:B	No Replacement
MT46H256M32R4JV-6 WT:B	No Replacement
MT46H64M32LFCX-48 IT:B	MT46H64M32LFBQ-48 IT:C
MT46H64M32LFCX-48 WT:B	MT46H64M32LFBQ-48 WT:C
MT46H64M32LFCX-5 AIT:B	MT46H64M32LFBQ-48 AIT:C
MT46H64M32LFCX-5 AT:B	No Replacement
MT46H64M32LFCX-5 IT:B	MT46H64M32LFBQ-48 IT:C
MT46H64M32LFCX-5 WT:B	MT46H64M32LFBQ-48 WT:C

Note: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change



---

<b>Affected Micron Part Number</b>	<b>Suggested Replacement Part</b>
MT46H64M32LFCX-6 AT:B	No Replacement
MT46H64M32LFCX-6 IT:B	MT46H64M32LFBQ-48 IT:C
MT46H64M32LFCX-6 WT:B	MT46H64M32LFBQ-48 WT:C
MT46H64M32LFMA-5 IT:B	No Replacement
MT46H64M32LFMA-5 WT:B	No Replacement
MT46H64M32LFMA-6 IT:B	No Replacement
MT46H64M32LFMA-6 WT:B	No Replacement

---

**Micron Sites Affected:** All Sites

---

**Last Time Buy:** 14-Mar-2014

---

**Last Time Ship:** 14-Sept-2014

---

Orders placed prior to the LTB date are subject to current inventory levels, which may vary based on market conditions and customer demand. Early orders are encouraged.