

MEMORANDUM

DATE: March 18, 2019

TO: Digi Key Corporation (001207)

SUBJECT: AT89LP51ED2 & AT89LP51ID2 Product Recall

Microchip Technology, Inc. (“Microchip”) routinely monitors manufacturing production control data as part of our

The affected devices listed in this recall notice have the on chip EEPROM function inadvertently disabled for the shipments listed below.

Microchip is therefore proactively requesting the return of any unused inventory from the affected shipments.

Please refer to the information below for the affected inventory shipped to your company and check this information against your records.

Microchip Catalog Part Number (CPN)	Lot Number
AT89LP51ID2-20AAU	190700681000ASE
AT89LP51ED2-20PU	191800124000ASSH
AT89LP51ID2-20AU	190800313000ASE
AT89LP51ED2-20MU	193600159000ASCL
AT89LP51ED2-20AAU	193800252000ASE
AT89LP51ED2-20JU	191400137000LPI
AT89LP51ED2-20JU	192000204000LPI
AT89LP51ED2-20AU	193700229000ASE
AT89LP51ED2-20JU	193900790000MMT
AT89LP51ED2-20MU	193600159000ASCL

Please contact your Microchip sales representative to coordinate the return and replacement of these devices.

Regards,

Microchip Technology, Inc.

THIS MESSAGE IS MICROCHIP CONFIDENTIAL INFORMATION PROVIDED ONLY FOR THE USE OF THE RECIPIENT(S). ANY DISSEMINATION, DISTRIBUTION, DUPLICATION OR OTHER USE IS STRICTLY PROHIBITED.