

# Product Announcement

September 22, 2016

## End of Life (EOL) # 092216

This announcement has been sent to notify you that the following product(s) have been discontinued and replaced.

**Final Order Date:** November 30, 2016

**Product Group Affected:** PLCC Series (SMP2, SMP4, SMP6)

## Description of Announcement:

To continue our commitment to produce innovative products with the highest quality standards and provide a streamlined ordering process, we'd like to inform you about the following changes to our product portfolio.

A detailed part number list has been provided on the following page(s) as notification of product(s) that are EOL and the replacement part number(s) that have been issued, if applicable.

Please email the Bivar Sales and Support Team with any questions concerning this announcement at [sales@bivar.com](mailto:sales@bivar.com).

<b>Part Number</b>	<b>Alternate Part Number</b>
SMP2-AC	SMTL2-AC
SMP2-BWC	SMTL2-BWC
SMP2-GC	SMTL2-GC
SMP2-HC	SMTL2-HC
SMP2-OC	SMTL2-OC
SMP2-PGC	SMTL2-PGC
SMP2-RC	SMTL2-RC
SMP2-SBWC	SMTL2-SBWC
SMP2-SGC	SMTL2-SGC
SMP2-SOC	SMTL2-SOC
SMP2-SPGC	SMTL2-SPGC
SMP2-SRC	SMTL2-SRC
SMP2-SUWD	SMTL2-SUWD
SMP2-SYC	SMTL2-SYC
SMP2-UPGC	SMTL2-UPGC
SMP2-URC	SMTL2-URC
SMP2-UWD	SMTL2-UWD
SMP2-UYC	SMTL2-UYC
SMP2-YC	SMTL2-YC
SMP4-BC	SMTL4-BC
SMP4-BC-RB	SMTL4-BC-RB
SMP4-BC-RY	SMTL4-BC-RY
SMP4-BC-YG	SMTL4-BC-YG
SMP4-RGB	SMTL4-RGB
SMP4-RGY	SMTL4-RGY
SMP4-RYB	SMTL4-RYB
SMP4-SBC	SMTL4-SBC
SMP4-SBC-RB	SMTL4-SBC-RB
SMP4-SBC-RY	SMTL4-SBC-RY
SMP4-SBC-YG	SMTL4-SBC-YG
SMP4-SRGB	SMTL4-SRGB
SMP4-SRGY	SMTL4-SRGY
SMP4-SRYB	SMTL4-SRYB
SMP6-BWC	SMTL6-BWC
SMP6-GC	SMTL6-GC
SMP6-RC	SMTL6-RC
SMP6-RGB	SMTL6-RGB
SMP6-UWDC	SMTL6-UWDC
SMP6-UWDN	SMTL6-UWDN
SMP6-UWDW	SMTL6-UWDW