


October 15, 2012

LF PCN# A0039B – Attachment A (257 Fuse Marking on Housing Top - ATOF Blade Fuse)

- The 257 and 287 fuse series share mold tooling, and will have the same housing markings.
- The 257 marking (outlined above) will be present in both series.
- The 257 marking, which has always been part of the mold tools (it is a hard tooled feature), has no impact on form, fit or function.
- There are no plans to remove this feature from the mold tools.

Please contact your local Littelfuse representative if you have any additional questions. We will be pleased to answer any questions you may have.

Thank you for your continued support.

Best Regards,

Littelfuse Automotive Business Unit