



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

PDN #: K-09-04 Last Buy Deadline for Submission of Order: 23-Mar-2010

Issue Date: 23-Mar-2009 Last Eligible Ship Date: 23-Jun-2010

Contact: Victor Abarca
 Title: Marketing Manager - PC Clock Products
 Phone #: 1-408-284-6578
 Fax #: 1-408-284-6596
 E-mail: victor.abarca@idt.com

PRODUCT(S) AFFECTED: ATTACHMENT Yes No

(List Replacement Part #(s), if any)

Selected Standard Packages of PC Clock devices will be discontinued and replaced by RoHS versions.
 See attachment I for affected part numbers and replacement part numbers.

REASON FOR DISCONTINUANCE:

- Replace slower speed with faster speed offerings Other: _____
- Obsolete Fab Technology / Process _____
- Obsolete Assembly Technology / Process _____
- Obsolete Package / Material _____
- Declined Market

CUSTOMER NOTIFICATION:

As a result of discontinuance reason(s) listed above, IDT has decided to discontinue certain products and notify you through this Product Discontinuance Notice (PDN). We recommend you to check detailed specifications before converting to equivalent devices offered. Please use acknowledgement below or E-Mail to request additional information.

Last time buy orders may be submitted any time prior to the date indicated above. All orders shall be subject to acceptance by IDT at its sole discretion unless otherwise agreed by IDT in writing.

If you have any questions, please feel free to contact your local IDT distributor or sales representative.

Customer: _____ E-Mail Address: _____
 Name/Date: _____ Phone#: _____
 Title: _____ Fax# : _____

CUSTOMER COMMENTS: _____

IDT ACKNOWLEDGEMENT:

Received By: _____ Date: _____



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS25210AG	None	ICS9112AM-26T	ICS9112AM-26LFT
ICS25210AGT	None	ICS9112AM-27	ICS9112AM-27LFT
ICS9107C-03CS14T	None	ICS9112AM-27T	ICS9112AM-27LFT
ICS9107C-03CS14T-IB0	None	ICS9112AM-28	ICS9112AM-28LFT
ICS9107C-03CS14T-IB1	None	ICS9112AM-28T	ICS9112AM-28LFT
ICS9107C-03CS14T-INT	None	ICS9112BF-17	ICS9112BF-17LFT
ICS9107C-05CS08	ICS9107C-05CS08LF	ICS9112BF-17T	ICS9112BF-17LFT
ICS9107C-05CS08T	ICS9107C-05CS08LFT	ICS9112BF-17T-IN0	ICS9112BF-17LNT-IN0
ICS9107C-05CS08T-MT0	None	ICS9112BG-17	None
ICS9107C-10CS08	ICS9107C-10CS08LF	ICS9112BG-17T	None
ICS9107C-10CS08T	ICS9107C-10CS08LFT	ICS9112BM-17	ICS9112BM-17LFT
ICS9107C-17CS08	ICS9107C-17CS08LF	ICS9112BM-17T	ICS9112BM-17LFT
ICS9107C-17CS08T	ICS9107C-17CS08LFT	ICS9112M-06	None
ICS9110-01CS14	ICS9110-01CS14LF	ICS9112M-06T	None
ICS9110-01CS14T	ICS9110-01CS14LFT	ICS9112M-07	ICS9112M-07LFT
ICS9110-01CS14T-A	None	ICS9112M-07T	ICS9112M-07LFT
ICS9110-02CS14	ICS9110-02CS14LF	ICS9112M-22	ICS9112M-22LFT
ICS9110-02CS14T	ICS9110-02CS14LFT	ICS9112M-22T	ICS9112M-22LFT
ICS9110-02CS14T-DE0	None	ICS9120-08CS08	None
ICS9110-02CS14T-IB0	None	ICS9120-08CS08T	None
ICS9111M-04	None	ICS9120M-45	None
ICS9111M-04T	None	ICS91305AG	ICS91305AGLF
ICS9112AF-17	ICS9112AF-17LF	ICS91305AGIT	ICS91305AGILFT
ICS9112AF-17T	ICS9112AF-17LFT	ICS91305AGT	ICS91305AGLFT
ICS9112AF-17T-IB0	ICS9112AF-17LFT-IB0	ICS91305AM	ICS91305AMLFT
ICS9112AF-17T-IB1	None	ICS91305AMI	ICS91305AMILFT
ICS9112AF-17T-IN0	None	ICS91305AMIT	ICS91305AMILFT
ICS9112AG-16	ICS9112AG-16LF	ICS91305AMT	ICS91305AMLFT
ICS9112AG-16T	ICS9112AG-16LFT	ICS91309AF	None
ICS9112AG-26	ICS9112AG-26LF	ICS91309AFI	None
ICS9112AG-26T	ICS9112AG-26LFT	ICS91309AFIT	None
ICS9112AG-26T-IN0	None	ICS91309AFT	None
ICS9112AG-27	ICS9112AG-27LF	ICS91309AGI	ICS91309AGILFT
ICS9112AG-27T	ICS9112AG-27LFT	ICS91309AGIT	ICS91309AGILFT
ICS9112AG-28	None	ICS91309AM	ICS91309AMLFT
ICS9112AG-28T	None	ICS91309AMI	ICS91309AMILFT
ICS9112AM-16	ICS9112AM-16LF	ICS91309AMIT	ICS91309AMILFT
ICS9112AM-16T	ICS9112AM-16LFT	ICS91309AMT	ICS91309AMLFT
ICS9112AM-16T-IB0	None	ICS91315BM	ICS91315BMLFT
ICS9112AM-16T-IN0	ICS9112AM-16LNT-IN0	ICS91315BMT	ICS91315BMLFT
ICS9112AM-16TV0	None	ICS9148AF-32	ICS9148AF-32LFT
ICS9112AM-17	ICS9112AM-17LF	ICS9148AF-32T	ICS9148AF-32LFT
ICS9112AM-17T	ICS9112AM-17LFT	ICS9148AF-58	None
ICS9112AM-26	ICS9112AM-26LF	ICS9148AF-58T	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS9148AG-12	ICS9148AG-12LF	ICS9159M-05T	ICS9159M-05LFT
ICS9148AG-12T	ICS9148AG-12LFT	ICS9159M-14	None
ICS9148AM-60	ICS9148AM-60LF	ICS9159M-14T	None
ICS9148AM-60T	ICS9148AM-60LFT	ICS9161A-01CW16	ICS9161A-01CW16LF
ICS9148BF-04	ICS9148BF-04LF	ICS9161A-01CW16T	ICS9161A-01CW16LFT
ICS9148BF-04T	ICS9148BF-04LFT	ICS9161A-01CW16T-IB0	None
ICS9148BF-17	ICS9148BF-17LF	ICS9161A-01CW16T-IB1	None
ICS9148BF-17T	ICS9148BF-17LFT	ICS9161A-01CW16T-IN0	None
ICS9148BF-26	ICS9148BF-26LF	ICS9169AM-70	None
ICS9148BF-26T	ICS9148BF-26LFT	ICS9169AM-70T	None
ICS9148BF-36	ICS9148BF-36LF	ICS9169M-01	ICS9169M-01LF
ICS9148BF-36T	None	ICS9169M-01T	ICS9169M-01LFT
ICS9148BF-37	ICS9148BF-37LF	ICS9170-01CS08	ICS9170-01CS08LF
ICS9148BF-37T	ICS9148BF-37LFT	ICS9170-01CS08T	ICS9170-01CS08LFT
ICS9148CF-10	ICS9148CF-10LF	ICS9170-02CS08	ICS9170-02CS08LF
ICS9148CF-10T	None	ICS9170-02CS08T	ICS9170-02CS08LFT
ICS9148F-02	ICS9148F-02LF	ICS9170-04CS08	ICS9170-04CS08LF
ICS9148F-12	ICS9148F-12LF	ICS9170-04CS08T	ICS9170-04CS08LFT
ICS9148F-12T	ICS9148F-12LFT	ICS9170-04CS08T-A	None
ICS9148F-18	ICS9148F-18LF	ICS9170-04CS08T-HP0	None
ICS9148F-18T	ICS9148F-18LFT	ICS9170-05CS08	None
ICS9148F-25	None	ICS9170-05CS08T	None
ICS9148F-25T	None	ICS91715AFT	None
ICS9154-16CS16	None	ICS91718BM	ICS91718BMLF
ICS9154A-04CS16	ICS9154A-04CS16LF	ICS91718CG	ICS91718CGLF
ICS9154A-04CS16T	ICS9154A-04CS16LFT	ICS91718CGT	ICS91718CGLFT
ICS9154A-27CS16	ICS9154A-27CS16LF	ICS91718CM	ICS91718CMLF
ICS9154A-27CS16T	ICS9154A-27CS16LFT	ICS91718CMT	ICS91718CMLFT
ICS9154A-27CS16T-IB0	None	ICS91719AG	ICS91719AGLF
ICS9154A-42CS16	None	ICS91719AG-SC0	ICS91719AGLF-SC0
ICS9154A-42CS16T	None	ICS91719AGT	ICS91719AGLFT
ICS9154A-57CS16	None	ICS91719AGT-SC0	ICS91719AGLFT-SC0
ICS9154A-57CS16T	None	ICS91719BG	ICS91719BGLF
ICS9155-01CW20	None	ICS91719BGT	ICS91719BGLFT
ICS9155-01CW20T	None	ICS9172-01CW16	ICS9172-01CW16LF
ICS9155-02CW20	None	ICS9172-01CW16T	ICS9172-01CW16LFT
ICS9155-02CW20T	None	ICS9172-03CS16	None
ICS9155C-01CW20	ICS9155C-01CW20LF	ICS9172-03CS16T	None
ICS9155C-01CW20T	ICS9155C-01CW20LFT	ICS9172-07CS16	None
ICS9155C-02CW20	None	ICS9172-07CS16T	None
ICS9155C-02CW20T	None	ICS91720BG	ICS91720BGLF
ICS9159C-02CW28	ICS9159C-02CW28LF	ICS91720BGT	ICS91720BGLFT
ICS9159C-02CW28T	ICS9159C-02CW28LFT	ICS91720BM	None
ICS9159M-05	ICS9159M-05LF	ICS91720BMT	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS9173-01CS08	ICS9173-01CS08LF	ICS9248AF-198T	ICS9248AF-198LFT
ICS9173-01CS08T	ICS9173-01CS08LFT	ICS9248AF-50	None
ICS9173-15CS08	ICS9173-15CS08LF	ICS9248AF-61	ICS9248AF-61LF
ICS9173-15CS08T	ICS9173-15CS08LFT	ICS9248AF-61T	ICS9248AF-61LFT
ICS91730AM	ICS91730AMLF	ICS9248AF-64	None
ICS91730AMT	ICS91730AMLFT	ICS9248AF-64T	ICS9248AF-64LFT
ICS9179AF-12	ICS9179AF-12LF	ICS9248AF-80	ICS9248AF-80LF
ICS9179AF-12T	ICS9179AF-12LFT	ICS9248AF-80T	ICS9248AF-80LFT
ICS9179AM-12	ICS9179AM-12LF	ICS9248AF-95	ICS9248AF-95LF
ICS9179BF-01	ICS9179BF-01LF	ICS9248AF-95T	ICS9248AF-95LFT
ICS9179BF-01T	ICS9179BF-01LFT	ICS9248AF-95T-IB0	None
ICS9179BF-03	ICS9179BF-03LF	ICS9248AF-96	ICS9248AF-96LF
ICS9179BF-03T	ICS9179BF-03LFT	ICS9248AF-96T	ICS9248AF-96LFT
ICS9179BG-03	None	ICS9248AG-101	ICS9248AG-101LF
ICS9179BG-03T	None	ICS9248AG-101T	ICS9248AG-101LFT
ICS9179CF-06	None	ICS9248AG-150	ICS9248AG-150LN
ICS9212AF-13	ICS9212AF-13LF	ICS9248AG-150T	ICS9248AG-150LNT
ICS9212AF-13T	ICS9212AF-13LFT	ICS9248AG-150T-IN0	None
ICS9212CF-01	ICS9212CF-01LF	ICS9248AG-185T	ICS9248AG-185LFT
ICS9212CF-01T	ICS9212CF-01LFT	ICS9248AG-188	ICS9248AG-188LF
ICS9212CF-03	None	ICS9248AG-188T	ICS9248AG-188LFT
ICS9212CF-03T	None	ICS9248AG-192	ICS9248AG-192LF
ICS9212CF-03T-IB0	None	ICS9248AG-192T	ICS9248AG-192LFT
ICS9222AG-01T-IN0	None	ICS9248AG-195	ICS9248AG-195LF
ICS9248AF-101	None	ICS9248AG-198	ICS9248AG-198LF
ICS9248AF-101T	None	ICS9248AG-198T	ICS9248AG-198LFT
ICS9248AF-114	None	ICS9248AG-92	ICS9248AG-92LF
ICS9248AF-114T	None	ICS9248AG-92T	ICS9248AG-92LFT
ICS9248AF-127	None	ICS9248AG-92T-IB0	None
ICS9248AF-127T	None	ICS9248AG-92T-IN0	None
ICS9248AF-128	ICS9248AF-128LF	ICS9248BF-102	ICS9248BF-102LF
ICS9248AF-128T	ICS9248AF-128LFT	ICS9248BF-102T	ICS9248BF-102LFT
ICS9248AF-150	ICS9248AF-150LF	ICS9248BF-137	None
ICS9248AF-150T	ICS9248AF-150LFT	ICS9248BF-137T	None
ICS9248AF-150T-IB0	None	ICS9248BF-138	ICS9248BF-138LF
ICS9248AF-151	ICS9248AF-151LF	ICS9248BF-138T	ICS9248BF-138LFT
ICS9248AF-151T	ICS9248AF-151LFT	ICS9248BF-146	ICS9248BF-146LF
ICS9248AF-173	None	ICS9248BF-146T	ICS9248BF-146LFT
ICS9248AF-173T	None	ICS9248BF-164	None
ICS9248AF-176	None	ICS9248BF-195	ICS9248BF-195LF
ICS9248AF-176T	None	ICS9248BF-195T	ICS9248BF-195LFT
ICS9248AF-185	None	ICS9248BF-20	ICS9248BF-20LF
ICS9248AF-185T	None	ICS9248BF-20T	ICS9248BF-20LFT
ICS9248AF-198	ICS9248AF-198LF	ICS9248BF-55	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS9248BF-55T	None	ICS9250BF-19	None
ICS9248BF-64	None	ICS9250BF-19T	None
ICS9248BF-64T	None	ICS9250BF-24	None
ICS9248BF-77	None	ICS9250BF-24T	None
ICS9248BF-77T	None	ICS9250BF-27	ICS9250BF-27LF
ICS9248BF-81	ICS9248BF-81LF	ICS9250BF-27T	ICS9250BF-27LFT
ICS9248BF-81T	ICS9248BF-81LFT	ICS9250BF-28	ICS9250BF-28LF
ICS9248BF-87	None	ICS9250BF-28T	ICS9250BF-28LFT
ICS9248BF-87T	None	ICS9250BF-50	ICS9250BF-50LF
ICS9248BF-96	ICS9248BF-96LF	ICS9250BF-50T	ICS9250BF-50LFT
ICS9248BF-96T	ICS9248BF-96LFT	ICS9250BG-24	ICS9250BG-24LF
ICS9248BF-99	None	ICS9250BG-24T	ICS9250BG-24LFT
ICS9248CF-126	ICS9248CF-126LF	ICS9250BG-24T-IN0	None
ICS9248CF-126T	ICS9248CF-126LFT	ICS9250CF-08	ICS9250CF-08LF
ICS9248CF-98	ICS9248CF-98LF	ICS9250CF-08T	ICS9250CF-08LFT
ICS9248CF-98T	ICS9248CF-98LFT	ICS9250CF-09	ICS9250CF-09LF
ICS9248DF-39	ICS9248DF-39LF	ICS9250CF-09T	ICS9250CF-09LFT
ICS9248DF-39T	ICS9248DF-39LFT	ICS9250CF-09T-IB0	None
ICS9248DF-39T-IB0	None	ICS9250CF-09T-IN0	None
ICS9248DF-54	None	ICS9250CF-10	ICS9250CF-10LF
ICS9248DF-54T	None	ICS9250CF-10T	ICS9250CF-10LFT
ICS9250AF-10	None	ICS9250DF-38	None
ICS9250AF-10T	None	ICS9250DF-38T	None
ICS9250AF-10T-IN0	None	ICS9250EG-38T	None
ICS9250AF-23	None	ICS9279AF-03	ICS9279AF-03LF
ICS9250AF-23T	None	ICS9279AF-03T	ICS9279AF-03LFT
ICS9250AF-25	ICS9250AF-25LF	ICS9279BF-01	None
ICS9250AF-25T	ICS9250AF-25LFT	ICS9279BF-01T	None
ICS9250AF-29	None	ICS932S200BF	ICS932S200BFLF
ICS9250AF-29T	None	ICS932S200BFT	ICS932S200BFLFT
ICS9250AF-30	ICS9250AF-30LF	ICS932S200BFT-CQ0	None
ICS9250AF-30T	ICS9250AF-30LFT	ICS932S200BFT-IN0	None
ICS9250AF-51	ICS9250AF-51LF	ICS932S200BG	None
ICS9250AF-51T	ICS9250AF-51LFT	ICS932S200BGT	None
ICS9250AG-31	None	ICS932S203AF	932S203AFLN
ICS9250AG-31T	None	ICS932S203AF	ICS932S203AFLF
ICS9250BF-09	None	ICS932S203AFT	932S203AFLNT
ICS9250BF-09T	None	ICS932S203AFT	ICS932S203AFLFT
ICS9250BF-10	None	ICS932S203AG	ICS932S203AGLF
ICS9250BF-10T	None	ICS932S203AGT	ICS932S203AGLFT
ICS9250BF-12	ICS9250BF-12LF	ICS932S203AGT-IN0	None
ICS9250BF-12T	ICS9250BF-12LFT	ICS932S203BF	None
ICS9250BF-16	ICS9250BF-16LF	ICS932S203BFT	None
ICS9250BF-16T	ICS9250BF-16LFT	ICS932S204AF	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS932S204AFT	None	ICS93722BF	ICS93722BFLF
ICS932S206AF	None	ICS93722BFT	ICS93722BFLFT
ICS932S206AFT	None	ICS93722CF	ICS93722CFLF
ICS932S208DF	ICS932S208DFLF	ICS93722CFT	ICS93722CFLFT
ICS932S208DFT	ICS932S208DFLFT	ICS93725AF	ICS93725AFLF
ICS932S208DFT-INO	None	ICS93725AFT	ICS93725AFLFT
ICS932S208DG	932S208DGLN	ICS93732AF	ICS93732AFLF
ICS932S208DG	ICS932S208DGLF	ICS93732AFT	ICS93732AFLFT
ICS932S208DGT	932S208DGLNT	ICS93732AG	None
ICS932S208DGT	ICS932S208DGLFT	ICS93732AGT	None
ICS932S208DGT-IB0	None	ICS93733CF	ICS93733CFLF
ICS932S208DGT-INO	None	ICS93733CFT	ICS93733CFLFT
ICS932S401EF	ICS932S401EFLF	ICS93734BFT	ICS93734BFLFT
ICS932S401EFT	ICS932S401EFLFT	ICS93735AF	ICS93735AFLF
ICS932S401EG	ICS932S401EGLF	ICS93735AFT	ICS93735AFLFT
ICS932S401EGT	ICS932S401EGLFT	ICS93738AF	ICS93738AFLF
ICS932S403AF	ICS932S403AFLF	ICS93738AFT	ICS93738AFLFT
ICS932S403AFT	ICS932S403AFLFT	ICS93741CF	None
ICS932S801AF	ICS932S801AFLF	ICS93741CFT	None
ICS932S801AFT	ICS932S801AFLFT	ICS93742AF	ICS93742AFLF
ICS932S801AG	ICS932S801AGLF	ICS93742AFT	ICS93742AFLFT
ICS932S801AGT	ICS932S801AGLFT	ICS93772AF	ICS93772AFLF
ICS9341AF	ICS9341AFLF	ICS93772AFT	ICS93772AFLFT
ICS9341AFT	ICS9341AFLFT	ICS93772CF	ICS93772CFLF
ICS9341AFT-IB0	None	ICS93772CFT	ICS93772CFLFT
ICS9342AF	ICS9342AFLF	ICS93776AF	None
ICS9342AFT	ICS9342AFLFT	ICS93776AFT	None
ICS93705AF	ICS93705AFLF	ICS93776BF	None
ICS93705AFT	ICS93705AFLFT	ICS93776BFT	None
ICS93705CF	ICS93705CFLF	ICS93777BF	ICS93777BFLF
ICS93705CFT	ICS93705CFLFT	ICS93777BFIT	None
ICS93712EF	ICS93712EFLF	ICS93777BFT	ICS93777BFLFT
ICS93712EFT	ICS93712EFLFT	ICS93786AF	ICS93786AFLF
ICS93716AF	ICS93716AFLF	ICS93786AFT	ICS93786AFLFT
ICS93716AFT	ICS93716AFLFT	ICS93789BF	ICS93789BFLF
ICS93716AFT-IB0	None	ICS93789BFT	ICS93789BFLFT
ICS93716AG	ICS93716AGLF	ICS93789DF	ICS93789DFLF
ICS93716AGT	ICS93716AGLFT	ICS93789DFT	ICS93789DFLFT
ICS93716BG	ICS93716BGLF	ICS94201DF	None
ICS93716BGT	ICS93716BGLFT	ICS94201DF-995	ICS94201DF-995LF
ICS93718CF	ICS93718CFLF	ICS94201DF-995T	ICS94201DF-995LFT
ICS93718CFT	ICS93718CFLFT	ICS94201DFT	ICS94201DFLFT
ICS93718DF	ICS93718DFLF	ICS94203AF	None
ICS93718DFT	ICS93718DFLFT	ICS94203AFT	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS94206BF	None	ICS950219BF	ICS950219BFLF
ICS94206BFT	None	ICS950219BFT	ICS950219BFLFT
ICS94211AF	ICS94211AFLF	ICS950220AF	ICS950220AFLF
ICS94211AFT	ICS94211AFLFT	ICS950220AFT	ICS950220AFLFT
ICS94215AF	None	ICS950220BF	ICS950220BFLF
ICS94215AFT	None	ICS950220BFT	ICS950220BFLFT
ICS94227AF	ICS94227AFLF	ICS950223BF	ICS950223BFLF
ICS94227AFT	ICS94227AFLFT	ICS950223BFT	ICS950223BFLFT
ICS94228BF	ICS94228BFLF	ICS950227AF	None
ICS94228BFT	ICS94228BFLFT	ICS950227AFT	None
ICS94230BF	ICS94230BFLF	ICS950227AFT-INO	None
ICS94230BFT	ICS94230BFLFT	ICS950401CF	ICS950401CFLF
ICS94230EF	None	ICS950401CFT	ICS950401CFLFT
ICS94230EFT	None	ICS950401CG	ICS950401CGLF
ICS94231AF	ICS94231AFLF	ICS950401CGT	ICS950401CGLFT
ICS94231AFT	ICS94231AFLFT	ICS950402AF	ICS950402AFLF
ICS94239CG	None	ICS950402AFT	ICS950402AFLFT
ICS94239CGT	None	ICS950402AG	ICS950402AGLF
ICS94241AF	ICS94241AFLF	ICS950402AGT	ICS950402AGLFT
ICS94241AFT	ICS94241AFLFT	ICS950403CF	ICS950403CFLF
ICS94252BF	ICS94252BFLF	ICS950403CFT	ICS950403CFLFT
ICS94252BFT	ICS94252BFLFT	ICS950405AF	ICS950405AFLF
ICS94258BF	None	ICS950405AFT	ICS950405AFLFT
ICS94258BFT	None	ICS950407AF	None
ICS94258BG	None	ICS950407AFT	None
ICS94258BGT	None	ICS950410AF	ICS950410AFLF
ICS950003DF	None	ICS950410AFT	ICS950410AFLFT
ICS950003DFT	None	ICS950410AG	ICS950410AGLF
ICS950201AF	ICS950201AFLF	ICS950410AGT	ICS950410AGLFT
ICS950201AFT	ICS950201AFLFT	ICS950602CF	ICS950602CFLF
ICS950201AG	ICS950201AGLF	ICS950602CFT	ICS950602CFLFT
ICS950201AGT	ICS950201AGLFT	ICS950602CG	ICS950602CGLF
ICS950202CF	ICS950202CFLF	ICS950602CGT	ICS950602CGLFT
ICS950202CFT	ICS950202CFLFT	ICS950802AF	ICS950802AFLF
ICS950209CF	None	ICS950802AFT	ICS950802AFLFT
ICS950209CFT	None	ICS950805AF	ICS950805AFLF
ICS950211AG	None	ICS950805AFT	ICS950805AFLFT
ICS950211AGT	None	ICS950805AG	ICS950805AGLF
ICS950211BF	ICS950211BFLF	ICS950805AGT	ICS950805AGLFT
ICS950211BFT	ICS950211BFLFT	ICS950805AGT-IB0	None
ICS950213AF	None	ICS950810BF	None
ICS950213AFT	None	ICS950810BFT	None
ICS950218AF	ICS950218AFLF	ICS950810BG	None
ICS950218AFT	ICS950218AFLFT	ICS950810BGT	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS950810CFT	None	ICS951001AFT	ICS951001AFLFT
ICS950810CG	ICS950810CGLF	ICS951402AF	ICS951402AFLF
ICS950810CGT	ICS950810CGLFT	ICS951402AFT	ICS951402AFLFT
ICS950810CGT-INO	None	ICS951402AG	ICS951402AGLF
ICS950810PG	ICS950810PGLF	ICS951402AGT	ICS951402AGLFT
ICS950810PGT	ICS950810PGLFT	ICS951403CF	None
ICS950810PGT-IB0	None	ICS951403CFT	None
ICS950811AG	ICS950811AGLF	ICS951403CG	None
ICS950811AGT	ICS950811AGLFT	ICS951403CGT	None
ICS950812CG	ICS950812CGLF	ICS951412AF	ICS951412AFLF
ICS950812CGT	ICS950812CGLFT	ICS951412AFT	ICS951412AFLFT
ICS950813BG	ICS950813BGLF	ICS951412AG	ICS951412AGLF
ICS950813BGT	ICS950813BGLFT	ICS951412AGT	ICS951412AGLFT
ICS950813CGT	ICS950813CGLFT	ICS951413CG	ICS951413CGLF
ICS950818AG	None	ICS951413CGT	ICS951413CGLFT
ICS950818AGT	None	ICS951416AF	ICS951416AFLF
ICS950822AG	ICS950822AGLF	ICS951416AFT	ICS951416AFLFT
ICS950822AGT	ICS950822AGLFT	ICS951416AG	ICS951416AGLF
ICS950901BF	ICS950901BFLF	ICS951416AGT	ICS951416AGLFT
ICS950901BFT	ICS950901BFLFT	ICS951417AF	ICS951417AFLF
ICS950902DF	ICS950902DFLF	ICS951417AFT	ICS951417AFLFT
ICS950902DFT	ICS950902DFLFT	ICS951418AG	None
ICS950902DG	ICS950902DGLF	ICS951418AGT	None
ICS950902DGT	ICS950902DGLFT	ICS951418BG	ICS951418BGLF
ICS950905AF	None	ICS951418BGT	ICS951418BGLFT
ICS950905AFT	None	ICS951420AF	ICS951420AFLF
ICS950908AF	None	ICS951420AFT	ICS951420AFLFT
ICS950908AFT	None	ICS951422AG	ICS951422AGLF
ICS950908AGT	None	ICS951422AGT	ICS951422AGLFT
ICS950908BF	ICS950908BFLF	ICS951601AF	ICS951601AFLF
ICS950908BFT	ICS950908BFLFT	ICS951601AFT	ICS951601AFLFT
ICS950908BG	ICS950908BGLF	ICS951702AGI	None
ICS950908BGT	ICS950908BGLFT	ICS951702AGIT	None
ICS950910AF	ICS950910AFLF	ICS951703AG	None
ICS950910AFT	ICS950910AFLFT	ICS951703AGT	None
ICS950913CF	ICS950913CFLF	ICS951704AG	None
ICS950913CFT	ICS950913CFLFT	ICS951704AGT	None
ICS950913CG	ICS950913CGLF	ICS951901AF	ICS951901AFLF
ICS950913CGT	ICS950913CGLFT	ICS951901AFT	ICS951901AFLFT
ICS950916BF	None	ICS952001AF	ICS952001AFLF
ICS950916BFT	None	ICS952001AFT	ICS952001AFLFT
ICS950917AF	ICS950917AFLF	ICS952001AG	None
ICS950917AFT	ICS950917AFLFT	ICS952001AGT	None
ICS951001AF	ICS951001AFLF	ICS952003AF	None



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS952003AFT	None	ICS952611BF	ICS952611BFLF
ICS952004AF	ICS952004AFLF	ICS952611BFT	ICS952611BFLFT
ICS952004AFT	ICS952004AFLFT	ICS952617BF	ICS952617BFLF
ICS952005CF	ICS952005CFLF	ICS952617BFT	ICS952617BFLFT
ICS952005CFT	ICS952005CFLFT	ICS952618BF	ICS952618BFLF
ICS952007AF	ICS952007AFLF	ICS952618BFT	ICS952618BFLFT
ICS952007AFT	ICS952007AFLFT	ICS952618BFT-INO	None
ICS952011BF	ICS952011BFLF	ICS952619CF	ICS952619CFLF
ICS952011BFT	ICS952011BFLFT	ICS952619CFT	ICS952619CFLFT
ICS952013CF	ICS952013CFLF	ICS952620CF	ICS952620CFLF
ICS952013CFT	ICS952013CFLFT	ICS952620CFT	ICS952620CFLFT
ICS952017AF	ICS952017AFLF	ICS952621CF	ICS952621CFLF
ICS952017AFT	ICS952017AFLFT	ICS952621CFT	ICS952621CFLFT
ICS952018AF	ICS952018AFLF	ICS952621CG	None
ICS952018AFT	ICS952018AFLFT	ICS952621CGT	None
ICS952019AF	ICS952019AFLF	ICS952623CG	ICS952623CGLF
ICS952019AFT	ICS952019AFLFT	ICS952623CGT	ICS952623CGLFT
ICS952023CG	ICS952023CGLF	ICS952635AF	ICS952635AFLF
ICS952023CGT	ICS952023CGLFT	ICS952635AFT	ICS952635AFLFT
ICS952101CF	ICS952101CFLF	ICS952635BF	ICS952635BFLF
ICS952101CF-EM0	None	ICS952635BFT	ICS952635BFLFT
ICS952101CFT	ICS952101CFLFT	ICS952638AF	None
ICS952101CFT-EM0	None	ICS952638AFT	None
ICS952302AG	ICS952302AGLF	ICS952642AF	ICS952642AFLF
ICS952302AGT	ICS952302AGLFT	ICS952642AFT	ICS952642AFLFT
ICS952501BF	None	ICS952643AF	ICS952643AFLF
ICS952501BFT	None	ICS952643AFT	ICS952643AFLFT
ICS952505AF	ICS952505AFLF	ICS952647AF	ICS952647AFLF
ICS952505AFT	ICS952505AFLFT	ICS952647AFT	ICS952647AFLFT
ICS952601EF	952601EFLN	ICS952702BF	ICS952702BFLF
ICS952601EF	ICS952601EFLF	ICS952702BFT	ICS952702BFLFT
ICS952601EFT	952601EFLNT	ICS952703BF	ICS952703BFLF
ICS952601EFT	ICS952601EFLFT	ICS952703BFT	ICS952703BFLFT
ICS952601EFT-IB0	None	ICS952801CF	ICS952801CFLF
ICS952601EFT-INO	952601EFLNT-INO	ICS952801CFT	ICS952801CFLFT
ICS952601EFT-INO	ICS952601EFLFT-INO	ICS952802AF	ICS952802AFLF
ICS952601EG	ICS952601EGLF	ICS952802AFT	ICS952802AFLFT
ICS952601EGT	ICS952601EGLFT	ICS952803AF	ICS952803AFLF
ICS952603DF	ICS952603DFLF	ICS952803AFT	ICS952803AFLFT
ICS952603DFT	ICS952603DFLFT	ICS952803AG	None
ICS952606PF	ICS952606PFLF	ICS952803AGT	None
ICS952606PFT	ICS952606PFLFT	ICS952805BF	ICS952805BFLF
ICS952607EF	ICS952607EFLF	ICS952805BFT	ICS952805BFLFT
ICS952607EFT	ICS952607EFLFT	ICS952903AF	ICS952903AFLF



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS952903AFT	ICS952903AFLFT	ICS954108CF	ICS954108CFLF
ICS952906AF	ICS952906AFLF	ICS954108CFT	ICS954108CFLFT
ICS952906AFT	ICS952906AFLFT	ICS954110BF	ICS954110BFLF
ICS952911BF	ICS952911BFLF	ICS954110BFT	ICS954110BFLFT
ICS952911BFT	ICS952911BFLFT	ICS954119DF	ICS954119DFLF
ICS952930HF	None	ICS954119DFT	ICS954119DFLFT
ICS952930HFT	None	ICS954120EF	ICS954120EFLF
ICS953001DF	None	ICS954120EFT	ICS954120EFLFT
ICS953001DFT	None	ICS954123BF	ICS954123BFLF
ICS953002CF	ICS953002CFLF	ICS954123BFT	ICS954123BFLFT
ICS953002CFT	ICS953002CFLFT	ICS954123CG	ICS954123CGLF
ICS953002DF	ICS953002DFLF	ICS954123CGT	ICS954123CGLFT
ICS953002DFT	ICS953002DFLFT	ICS954124AF	ICS954124AFLF
ICS953008BF	ICS953008BFLF	ICS954124AFT	ICS954124AFLFT
ICS953008BFT	ICS953008BFLFT	ICS954124BF	None
ICS953009AF	ICS953009AFLF	ICS954124BFT	ICS954124BFLFT
ICS953009AFT	ICS953009AFLFT	ICS954127BF	ICS954127BFLF
ICS953201BF	ICS953201BFLF	ICS954127BFT	ICS954127BFLFT
ICS953201BFT	ICS953201BFLFT	ICS954127BG	ICS954127BGLF
ICS953202BF	ICS953202BFLF	ICS954127BGT	ICS954127BGLFT
ICS953202BFT	ICS953202BFLFT	ICS954128AF	ICS954128AFLF
ICS953202BG	None	ICS954128AFT	ICS954128AFLFT
ICS953202BGT	None	ICS954129BF	ICS954129BFLF
ICS953401CF	ICS953401CFLF	ICS954129BFT	ICS954129BFLFT
ICS953401CFT	ICS953401CFLFT	ICS954130BF	ICS954130BFLF
ICS953401CG	None	ICS954130BFT	ICS954130BFLFT
ICS953401CGT	None	ICS954135AF	ICS954135AFLF
ICS953803AFT	None	ICS954135AFT	ICS954135AFLFT
ICS953805CF	ICS953805CFLF	ICS954141AF	ICS954141AFLF
ICS953805CFT	ICS953805CFLFT	ICS954141AFT	ICS954141AFLFT
ICS953805CG	ICS953805CGLF	ICS954141AG	ICS954141AGLF
ICS953805CGT	ICS953805CGLFT	ICS954141AGT	ICS954141AGLFT
ICS954101DF	954101DFLN	ICS954141BF	ICS954141BFLF
ICS954101DF	ICS954101DFLF	ICS954141BFT	ICS954141BFLFT
ICS954101DFT	954101DFLNT	ICS954141BG	ICS954141BGLF
ICS954101DFT	ICS954101DFLFT	ICS954141BGT	ICS954141BGLFT
ICS954101DFT-INO	None	ICS954148AF	ICS954148AFLF
ICS954101DG	ICS954101DGLF	ICS954148AFT	ICS954148AFLFT
ICS954101DGT	ICS954101DGLFT	ICS954201AG	ICS954201AGLN
ICS954102AF	ICS954102AFLN	ICS954201AGT	ICS954201AGLNT
ICS954102AFT	ICS954102AFLNT	ICS954201BF	ICS954201BFLF
ICS954102AFT-INO	ICS954102AFLNT-INO	ICS954201BFT	ICS954201BFLFT
ICS954105BF	ICS954105BFLF	ICS954201BG	ICS954201BGLF
ICS954105BFT	ICS954105BFLFT	ICS954201BGT	ICS954201BGLFT



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS954201CG	None	ICS9DB104AF	ICS9DB104AFLF
ICS954201CGT	None	ICS9DB104AFT	9DB104AFLNT
ICS954203AGT	ICS954203AGLFT	ICS9DB104AFT	ICS9DB104AFLFT
ICS954203BG	ICS954203BGLF	ICS9DB104AFT-IN0	None
ICS954203BGT	ICS954203BGLFT	ICS9DB104AG	9DB104AGLN
ICS954204AGT	954204AGLNT	ICS9DB104AG	ICS9DB104AGLF
ICS954204AGT	ICS954204AGLFT	ICS9DB104AGT	9DB104AGLNT
ICS954204BGT	954204BGLNT	ICS9DB104AGT	ICS9DB104AGLFT
ICS954204BGT	ICS954204BGLFT	ICS9DB104BF	9DB104BFLN
ICS954204CG	954204CGLN	ICS9DB104BF	ICS9DB104BFLF
ICS954204CG	ICS954204CGLF	ICS9DB104BFT	9DB104BFLNT
ICS954204CGT	954204CGLNT	ICS9DB104BFT	ICS9DB104BFLFT
ICS954204CGT	ICS954204CGLFT	ICS9DB104BFT-IN0	ICS9DB104BFLNT-IN0
ICS954206AG	ICS954206AGLF	ICS9DB104BG	9DB104BGLN
ICS954206AGT	ICS954206AGLFT	ICS9DB104BG	ICS9DB104BGLF
ICS954206BF	ICS954206BFLF	ICS9DB104BGT	9DB104BGLNT
ICS954206BFT	ICS954206BFLFT	ICS9DB104BGT	ICS9DB104BGLFT
ICS954206BG	ICS954206BGLF	ICS9DB108AF	ICS9DB108AFLF
ICS954206BGT	ICS954206BGLFT	ICS9DB108AFT	ICS9DB108AFLFT
ICS954211AF	ICS954211AFLF	ICS9DB108AFT-IN0	None
ICS954211AFT	ICS954211AFLFT	ICS9DB108AG	ICS9DB108AGLF
ICS954213AGT	ICS954213AGLFT	ICS9DB108AGT	ICS9DB108AGLFT
ICS954215AG	ICS954215AGLF	ICS9DB108AGT-IN0	None
ICS954215AGT	ICS954215AGLFT	ICS9DB108BF	9DB108BFLN
ICS954217AG	ICS954217AGLF	ICS9DB108BF	ICS9DB108BFLF
ICS954217AGT	ICS954217AGLFT	ICS9DB108BFT	9DB108BFLNT
ICS954218BG	ICS954218BGLF	ICS9DB108BFT	ICS9DB108BFLFT
ICS954218BGT	ICS954218BGLFT	ICS9DB108BFT-IB0	None
ICS954226AG	ICS954226AGLF	ICS9DB108BFT-IN0	None
ICS954226AGT	ICS954226AGLFT	ICS9DB108BG	ICS9DB108BGLF
ICS954229AGT	ICS954229AGLFT	ICS9DB108BGT	ICS9DB108BGLFT
ICS954306BG	ICS954306BGLF	ICS9DB108BGT-IN0	None
ICS954306BGT	ICS954306BGLFT	ICS9DB124AFT	None
ICS954511BF	ICS954511BFLF	ICS9DB124AGT	None
ICS954511BFT	ICS954511BFLFT	ICS9DB401BF	ICS9DB401BFLF
ICS954550AG	None	ICS9DB401BFT	ICS9DB401BFLFT
ICS954550AGT	None	ICS9DB401BG	ICS9DB401BGLF
ICS960001AF	ICS960001AFLF	ICS9DB401BGT	ICS9DB401BGLFT
ICS960001AFT	ICS960001AFLFT	ICS9DB801BF	ICS9DB801BFLF
ICS960002AF	ICS960002AFLF	ICS9DB801BFT	ICS9DB801BFLFT
ICS960002AFT	ICS960002AFLFT	ICS9DB801BG	ICS9DB801BGLF
ICS960010AF	ICS960010AFLF	ICS9DB801BGT	ICS9DB801BGLFT
ICS960010AFT	ICS960010AFLFT	ICS9FG104CF	ICS9FG104CFLF
ICS9DB104AF	9DB104AFLN	ICS9FG104CFT	ICS9FG104CFLFT



Integrated Device Technology, Inc.
 6024 Silver Creek Valley Road, San Jose, CA 95138
 Phone #: (408) 284-8200

PRODUCT DISCONTINUANCE NOTICE (PDN)

ATTACHMENT I - PDN #: K-09-04

Affected Part Number

Discontinued Part#	Replacement Part#	Discontinued Part#	Replacement Part#
ICS9FG104CG	ICS9FG104CGLF	IDTCV110NPV8	IDTCV110NPVG8
ICS9FG104CGT	ICS9FG104CGLFT	IDTCV115-2PV	IDTCV115-2PVG
ICS9FG107AFT	None	IDTCV115-2PV8	IDTCV115-2PVG8
ICS9FG107AG	ICS9FG107AGLN	IDTCV115-4PV	IDTCV115-4PVG
ICS9FG107AGT	ICS9FG107AGLNT	IDTCV115-4PV8	IDTCV115-4PVG8
ICS9FG107AGT-IB0	None	IDTCV115CPV	IDTCV115CPVG
ICS9FG108CF	ICS9FG108CFLF	IDTCV115CPV8	IDTCV115CPVG8
ICS9FG108CFT	ICS9FG108CFLFT	IDTCV115FPV	IDTCV115FPVG
ICS9FG108CG	ICS9FG108CGLF	IDTCV115FPV8	IDTCV115FPVG8
ICS9FG108CGT	ICS9FG108CGLFT	IDTCV123PV	IDTCV123PVG
ICS9FG110CF	ICS9FG110CFLF	IDTCV123PV8	IDTCV123PVG8
ICS9FG110CFT	ICS9FG110CFLFT	IDTCV125PA	IDTCV125PAG
ICS9FG110CG	ICS9FG110CGLF	IDTCV125PA8	IDTCV125PAG8
ICS9FG110CGT	ICS9FG110CGLFT	IDTCV126PA	IDTCV126PAG
ICS9FG1201CF	ICS9FG1201CFLF	IDTCV126PA8	IDTCV126PAG8
ICS9FG1201CFT	ICS9FG1201CFLFT	IDTCV132APV	IDTCV132APVG
ICS9FG1201CG	ICS9FG1201CGLF	IDTCV132APV8	IDTCV132APVG8
ICS9FG1201CGT	ICS9FG1201CGLFT	IDTCV133PA	IDTCV133PAG
ICS9FG1201CGT-IN0	ICS9FG1201CGLFT-IN0	IDTCV133PA8	IDTCV133PAG8
ICS9FG1202CF	ICS9FG1202CFLF	IDTCV136PA	IDTCV136PAG
ICS9FG1202CFT	ICS9FG1202CFLFT	IDTCV136PA8	IDTCV136PAG8
ICS9FG1202CG	ICS9FG1202CGLF	IDTCV137PA	IDTCV137PAG
ICS9FG1202CGT	ICS9FG1202CGLFT	IDTCV137PA8	IDTCV137PAG8
ICS9LP208AG	ICS9LP208AGLF	IDTCV140PA	IDTCV140PAG
ICS9LP208AGT	ICS9LP208AGLFT	IDTCV140PA8	IDTCV140PAG8
ICS9P750CG	ICS9P750CGLF	IDTCV141PA	IDTCV141PAG
ICS9P750CGT	ICS9P750CGLFT	IDTCV141PA8	IDTCV141PAG8
ICS9P932CF	ICS9P932CFLF	IDTCV141PV	IDTCV141PVG
ICS9P932CFT	ICS9P932CFLFT	IDTCV141PV8	IDTCV141PVG8
ICS9P933DF	ICS9P933DFLF	IDTCV143PY	IDTCV143PYG
ICS9P933DFT	ICS9P933DFLFT	IDTCV143PY8	IDTCV143PYG8
ICS9P937AF	None	IDTCV144PA	IDTCV144PAG
ICS9P937AFT	None	IDTCV144PA8	IDTCV144PAG8
ICSCLK756J40F	ICSCLK756J40FLF	IDTCV146PV	IDTCV146PVG
ICSCLK756J40FT	ICSCLK756J40FLFT	IDTCV146PV8	IDTCV146PVG8
ICSCLK865J02F	ICSCLK865J02FLF	IDTCV149PA	IDTCV149PAG
ICSCLK865J02FT	ICSCLK865J02FLFT	IDTCV149PA8	IDTCV149PAG8
IDTCV110JPA	None		
IDTCV110JPA8	None		
IDTCV110JPV	IDTCV110JPVG		
IDTCV110JPV8	IDTCV110JPVG8		
IDTCV110LPV	IDTCV110LPVG		
IDTCV110LPV8	IDTCV110LPVG8		
IDTCV110NPV	IDTCV110NPVG		