



Product Discontinuance Notice - PDN 21_0135 Rev. A

Analog Devices, Inc. One Analog Way, Wilmington, MA 01887

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

Discontinuation of ADIS16448

Publication Date: 17-Dec-2021

Last Time Buy Date: 25-Feb-2022

Last Time Ship Date: 15-Sep-2023

Revision Description:

Extend Last Time Buy date.

Reason For Discontinuance

Obsolescence of magnetometer component within the 16448. Shortage is severe, requiring shorter LTB period.

Comments

The ADIS16448 contains a magnetometer sourced externally which has been obsoleted. There is no option to replace it. Supply is severely limited, thus the 16448 is being discontinued. The ADIS16446 is a pin compatible option, which does not contain the magnetometer or the barometer.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 21_0135 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
ADIS16448BMLZ	ADIS16448	see comments	yes	ADIS16446 does not contain the magnetometer nor the barometer
ADIS16448BMLZ-P	ADIS16448	see comments	yes	ADIS16446 does not contain the magnetometer nor the barometer

Appendix A - PDN 21_0135 Revision History

Rev	Publish Date	Rev Description
Rev. -	15-Sep-2021	Initial Release
Rev. A	17-Dec-2021	Extend Last Time Buy date.

Analog Devices, Inc. Proprietary Information

DocId:1764 Layout Rev:3 Parent DocId:None